

Community Advisory Group (CAG)
Hudson River PCBs Superfund Site
DRAFT Meeting Agendas
9 December 2004
Air Monitoring, 10:00 AM to 12:00 PM
CAG Meeting, 1:00 PM – 4:00 PM
Waterford, NY
Peebles Island State Park

OPTIONAL: CAG Detailed Discussion on Air and Noise Monitoring

- 10:00 pm Presentation and Discussion of Air Monitoring Issues**
- State air standards for PCBs
 - Basis for Quality of Life Performance Standards for PCBs in Air
 - Baseline monitoring duration and purpose
 - Dewatering facility and area
 - Dredging area
 - Role of CHASP and On-Site Worker Health and Safety Plan

12:00 pm LUNCH BREAK

CAG MEETING

- 1:00 Welcome, Review Groundrules for Meeting**
- 1:05 Meeting Summary and Action Item Update**
- September Meeting summary corrections and approval and Action Items
- 1:15 New Bedford Site Tour Debriefing and Fox River Video**
- Members and EPA Debrief New Bedford Site Tour
 - View Fox River Video
- 1:45 Monitoring AM Meeting Debriefing**
- Members and EPA, DEC, DH Debrief Morning Discussion
 - Questions
- 2:15 Break**
- 2:30 Host Community Benefits**
- Introduction of issue by John Lawler
 - Discussion

3:00

2005 Preview

- EPA Presentation and Discussion
- Issues to Ponder:
 - Meeting Frequency
 - Review of earlier draft documents
 - Other agenda topics outside the Road Map
 - Agenda Planning Group
 - Subcommittees
 - Occasional meetings w/o liaisons
 - Meeting Locations
 - Other

3:30

Brief Updates

- Facility Siting Update – EPA
- Floodplain investigation update - EPA
- Agricultural Working Group update -- EPA

3:50

Public Comment

3:55

Potential Agenda Items for Next CAG Meeting, January 27, 2005

- Dredge Area Delineation Report
- Facility Siting
- Interagency Working Group Workshop Debrief

4:00

Adjourn