







Dredging Project Update







Dredging Project Update

- Dredging started May 15, 2009
- Video










Certification Units





Update on Phase 1 Dredging Progress

River Operations:

- Rock Dike and Silt Curtain In-Place
- Tree Trimming (complete)
- Debris Removal (complete)
 - Additional debris removal will be done as needed if large debris is encountered
- Dredging Underway
 - West Channel at Rogers Island
 - East Channel at Rogers Island














Update on Phase 1 Dredging Progress

River Operations:

- Sheet Pile Wall Near Griffin Island (40% Complete)
- Upcoming activities
 - Residual dredging
 - Certification unit review/approval
 - Backfilling/capping

Facility Operations:

- Up to 6 barges can be staged
- Start 24 hour operation last Saturday
- Rail car loading









Productivity

 Approximately 16,400 cubic yards inventory dredged as of June 13, 2009





Far-field Water Monitoring Data




Performance Standard Monitoring

Monitoring along river and at processing facility









Monitoring Exceedances

- Some noise exceedances in east channel
- One air exceedance at facility
- Several air exceedances:
 - one in west channel
 - two in east channel





EPA's Monitoring Data Website

- EPA has created a website for the performance standard monitoring data that is being generated as part of Phase 1 dredging and sediment processing facility operations.
- www.hudsondredgingdata.com



